Approved For Release 2002/01/23 CIA-RDP77M00144R000300070012-2

24 JUL 1975

Soviet Fast Breeder Reactor at Shevchenko Experiences Another Steam Generator Failure

In February, one of the recently repaired steam generators on the BN-350 liquid-metal fast breeder reactor (LMFBR) located at Shevchenko experienced a massive failure. After only 7 days of operation about 700 liters of water entered the sodium side of the steam generator. Temperatures reached 800-900°C because of the sodium-water reaction. High temperature caustic corrosion damaged 120 tubes. The cause of this steam generator failure was believed to be defective tube material since the end caps and welds had undergone extensive nondestructive testing.

Comment:

Lack of adequate quality control has plagued Soviet development of a reliable steam generator for LMFBRs. This is the fourth steam generator failure for the BN-350, and it could delay the full-power operation of the reactor by as much as a year. The causes of the first three failures were attributed to poor welding and inadequate inspection procedures. Since the fourth failure has been attributed to defective tube material, it is not known whether the Soviets will continue with their program to retube the steam generators with the existing supply of field tubes or whether new tubes will be ordered.

SECRET

<u> Appration in the legise is 000248 1/1234 TCIA - RIPPATIMEN 1/14 IR 00030</u>0070012-2 UNCLASSIFIED CONFIDENTIAL SECRET OFFICIAL ROUTING SLIP то DATE INITIALS 1 2 3 4 5 **ACTION** DIRECT REPLY PREPARE REPLY **APPROVAL** DISPATCH RECOMMENDATION COMMENT FILE RETURN CONCURRENCE INFORMATION SIGNATURE Remarks: This is the brief item I spoke to you about today thought Geor FOLD HERE TO RETURN TO SENDER FROM: NAME, ADDRESS AND PHONE NO. DATE 02/01/23 CHA-RI CONFIDENTIAL <u>00144R000</u>\$00070012-2

SECRET

25X1A

25X1A

25X1A

UNGLASSIFIED

FORM NO. 237 Use previous editions